


Whinfield - Holebiggerah FP 563007: Survey by MC & PQ





Survey date: 16th August 2025




Notes:

- Each point in the table below has a clickable link to the photos at that point. [Click here for All Photos.](#)
- Abbreviations: ROW = right of way, FP = footpath, WM = waymark, NW = northwest, NE – northeast, etc.

FP 563005 : Cowran to Whinfield:

Location	Status	Action(s)?	Photos
P1: Where this FP and BW 563008 leave the end of the lane at Whinfield. SD 25210 76585	<ul style="list-style-type: none">• Is there a fingerpost here with fingers for both the BW and FP? Need to check this as my notes weren't clear.	<ul style="list-style-type: none">• Check for fingerpost here.	 Full Photos

<p>P2: Gateway with adjacent wicket gate.</p> <p>SD 25215 76619</p>	<ul style="list-style-type: none"> • Wicket gate has only 50cm gap width. But adjacent wooden gate into private drive looks like it stays open. • No WMs either way. 	<ul style="list-style-type: none"> • Add WMs. 	 <p>Full Photos</p>
<p>P3: Metal field gate across private drive.</p> <p>SD 25211 76691</p>	<ul style="list-style-type: none"> • Gate looks like it is always open or at least openable. • No WMs but none needed here as there is only one way to go. 	<ul style="list-style-type: none"> • None 	 <p>Full Photos</p>
<p>P4: Wooden field gate + adjacent wooden step stile.</p> <p>SD 25230 76754</p>	<ul style="list-style-type: none"> • Step stile is a bit overgrown with nettles but reasonably firm and usable. • Step stile has reasonably clear WMS on both sides. • Adjacent wooden field gate is openable. 	<ul style="list-style-type: none"> • Clear nettles from stile. 	 <p>Full Photos</p>
<p>P5: Collapsed wooden step stile over barbed-wire-topped fence.</p> <p>SD 25367 76884</p>	<ul style="list-style-type: none"> • Completely impassable, since stile has almost completely collapsed and all that remains are evidence of its side posts and its top rail, but there are no step(s) or step posts. • Third photo is a few yards east of the stile, where an agile person can just about cross the 	<ul style="list-style-type: none"> • Install completely new wooden step stile. 	 <p>Full Photos</p>

	fence with the help of a wooden fence to hold onto, but it is dangerous trying to do that.		
P6: Field gate into next field. SD 25481 77001	<ul style="list-style-type: none"> • On survey day the gate was open but blocked by cattle (1st photo). And in the past this gateway has sometimes been flooded and/or extremely muddy from cattle gathering there. • However, there is an alternative route, by going right through another gate just before (not visible in photos) into the adjacent field, and then back through a 3rd gate (2nd photo) out of that field to reach the other side of this 1st gate. But that whole area can be very wet. • Two WMs on gatepost. Oddly they point in slightly different directions but there is only one ROW goes through this gateway. 	<ul style="list-style-type: none"> • Improve drainage? • Ask farmer to not feed cattle there? 	 <p>Full Photos</p>
P7: Metal field gate into next field. SD 25482 77103	<ul style="list-style-type: none"> • Gate was open and looks like it normally is. • No WMs. 	<ul style="list-style-type: none"> • Perhaps don't really need WMs here. 	 <p>Full Photo</p>
P8: Metal field gate onto lane at Holebiggerah. SD 25499 77285	<ul style="list-style-type: none"> • Gate is openable. • No WMs & no fingerpost. 	<ul style="list-style-type: none"> • Add WMs. • Council should add fingerpost. 	 <p>Full Photo</p>